



2024 F-15 TCP WWR



F-15 Secondary Power System (SPS) Updates

19 Nov. 2024

Disclosure Notice: This information is furnished on the condition that it will not be released to another nation without specific authority of the Department of the Air Force of the United States, that it will be used for military purposes only, that individual or corporate rights originating in the information, whether patented or not, will be respected, that the recipient will report promptly to the United States any known or suspected compromise, and that the information will be provided substantially the same degree of security afforded it by the Department of Defense of the United States. Also, regardless of any other markings on the document, it will not be downgraded or declassified without written approval of the originating U.S. agency.

This briefing, presentation, or document is for information only. No US Government commitment to sell, loan, lease, co-develop or co-produce defense articles or provide defense services is implied or intended.

Daniel Newquist 419th SCMS/GUEA DSN: 586-3788 Daniel.newquist.1@us.af.mil





Disclosure Statement

"This information is furnished on the condition that it will not be released to another nation without specific authority of the Department of the Air Force of the United States, that it will be used for military purposes only, that individual or corporate rights originating in the information, whether patented or not, will be respected, that the recipient will report promptly to the United States any known or suspected compromise, and that the information will be provided substantially the same degree of security afforded it by the Department of Defense of the United States. Also, regardless of any other markings on the document, it will not be downgraded or declassified without written approval of the originating US Agency, AFLCMC/WAQIB - TCP, 320 Richard Ray Blvd, Robins AFB GA 31098-1670".

This briefing is for information only. No US Government commitment to sell, loan, lease, co-develop or co-produce defense articles or provide defense service is implied or intended."





Overview

- **■**Power Take Off (PTO) Shaft Redesign
- Jet Fuel Starter (JFS) Mechanical Switch Elimination (-8 JFS)
- **■**Central Gear Box (CGB) Clutch and Brake Upgrade





Background:

- ■PTO redesign effort began August of 2016 to address main engine gearbox cracking issues and low reliability
- ■Spline and pilot wear #1 reason for return
- ■PTO MTBO is 300-400 hours; Far less than the 1200 hour designed life
- ■Issues Identified:
 - Dissimilar material hardness
 - ■Inadequate spline lubrication
 - ■Relative axial motion







19E173-6A Improvements:

- ■Increased wear resistance
- Distributed loading more evenly
- Shift axial resonant frequencies out of operating range
- Improved ball and socket assembly
- ■Longer life nut plates (100 uses vs. legacy 10-15 uses)
- Offset bolt hole 2 degrees between input and output coupling
- ■AMAD/PTO lubrication system components upgraded to increase spline lubrication
 - ■PTO Output Coupling
 - AMAD PTO Gearshaft

- AMAD PTO Bearing Cover
- AMAD PTO Bearing Carrier





Current Status of Redesign:

- ■PTO/AMAD testing at Honeywell- Completed
- PTO Acceptance/Qualification Testing- Completed
- ■PTO Engineering Review and Airworthiness- Completed
- ■Upgrade of 4 AMADs- Completed
- ■AMAD Endurance Testing- In Progress
- ■AMAD Engineering Review and Airworthiness- In Progress
- Field Service Evaluation- In Progress






Field Service Evaluation:

- ■Test Plan
 - ■200+ hour test with multiple inspections (every 50 flight hours)
 - ■4 shafts with 2 new and 2 legacy AMAD configuration
 - ■Also will collect data on two -4A PTO shafts with two upgraded AMADs
 - ■Data will be collected on both -220 and -229 engines
- **■Status**
 - ■2 of the 4 shafts are currently flying and have over 400 and 800 hours
 - ■Both shafts are paired with legacy AMADs
 - ■Current wear trends for both shafts put expected life well beyond 1200 hour goal before falling below spline wear limit
- ■FSE with 2 remaining upgraded PTO shafts and upgraded AMADs expected to begin March 2025 after AMAD endurance testing











PTO Shaft 0003 After 600 Hours of Use








Upcoming Schedule	ECD
TO Updates (Commodity and Aircraft)	January 2025
USAF Contracting and Ordering of New Shaft	February 2025
AMAD Endurance Testing	March 2025
FSE with Remaining PTOs and AMAD configurations	December 2025
Final Fielding Configuration Control Board (CCB) Review	December 2025
USAF Field New PTO Shaft	February 2027



JFS Mechanical Switch Elimination **Project** U.S. AIR FORCE



- Began modifications during depot overhaul April 2016
- Project addressed leading cause of F-15 ground aborts related to SPS:
 - Aircraft Mounted Accessory Drive (AMAD) 50% switches
 - ■JFS 2-speed switch
 - ■JFS wire harness
- ■Switch functionality was incorporated into the new **Generator Control Unit (GCU)**





JFS Mechanical Switch Elimination Project



Discussion Cont.

- Implementation through JFS modification
 - ■Old JFS Part Number: 384238-7-1
 - ■New JFS Part Number: 384238-8-1
 - See Figures on subsequent slide for changes
 - Modification accomplished at Depot
- ■384238-8-1 JFS is compatible with all aircraft configurations
- ■Full benefit results from a modified JFS and aircraft wiring


■Status

- ■USAF depot modification began April 2016. Due to part supply issues, modification was stopped for multiple years
- USAF modification program is still in progress
- Additional field time needed to quantify reliability improvements



JFS Mechanical Switch Elimination Project








JFS Mechanical Switch Elimination **Project** U.S. AIR FORCE




- ■New GCU has had some reported "no-start" issues
 - ■21 GCUs, either from the field or identified at depot, have been confirmed as malfunctioning
 - **■OEM Investigation Results**
 - "No-start" issues found to be due to a failed power supply
 - ■Power Supply Investigation found failed fuses, some of which were miswired during production causing early failure
 - OEM implementing check to ensure proper wiring going forward
 - Causes of other failures unknown
- USAF will continue to monitor issue but reported "no start" issues have slowed with none reported for over 2 years







CGB Clutch and Brake Upgrade



- Description
 - ■Clutch provides mechanical linkage to AMAD during main engine startup
- **■**Issue
 - Clutch and brake wear causing early CGB returns







CGB Clutch and Brake Upgrade

Discussion

- ■Clutch and Brake wear estimated to be cause for ~50% of all CGB returns to depot
- ■Prior to PBL contract, an overhauled Thomas Instrument clutch and brake (87060-01) was used at USAF depot
 - ■Baseline tested the overhauled clutch 87060-01 on a CGB (1 test)
 - Reached 273 engagements stopped for vibration issues
 - **■**Extrapolated results suggest <500 engagements
 - **■**Limiting factor is the brake
 - Test replicated results from bench testing
- ■New Clutch and Brake
 - ■Thomas Instrument developed a new friction material to increase service life, "2X clutch"
 - ■Baseline tested the "2X clutch" on a CGB at Honeywell test cell
 - ■Tested to 800 engagements with measurements every 200
 - **■**Extrapolated results suggest >1500 engagements with the brake failing first
 - ■Test replicated results from bench testing






CGB Clutch and Brake Upgrade

■Status

- Material Analysis completed on new friction material
- ■Engineering Review/Airworthiness Complete and approved for use
- ■New part numbers have been added to the **IPB**
 - ■88448-10: 2X Clutch and Brake Assembly
 - ■88371-10: 2X Disk Assembly
 - **■**88376-10: 2X Brake Flange
- ■USAF working with Honeywell for implementation under PBL contact
 - Approximately 50 2X Clutches installed in CGBs
 - **■**Four currently near or over 1000 engagements
 - Additional field time needed to quantify reliability improvements







Questions